Annexure- D

## BUILDING SAFETY CERTIFICATE-

No. PWD/DB/524/2026. Dated : 24/09/2026

It is Certified that the Existing building **Principal, Indian Model International School, Solapur** at Survey No. 99/7, Near vivekanand Kendra, Majrewadi, Jule Solapur, Dist- Solapur is having Block (s) / Floor (S) as per details below :

| Details of Block (S) in School | Block (1) | Block (2) | Block (3) | Block (4) | Block (5) | Block (6) |
|---|---|---|---|---|---|---|
| No. of Floor (S) in the Block | **Ground Floor + 4 Floors** | - | - | - | - | - |

The building is owned/occupied by **Indian Model International School, Solapur** at Survey No. 99/7, Near vivekanand Kendra, Majrewadi, Jule Solapur, Dist-Solapur have complied with the building safety requirements in accordance with National Building code Rules and verified by the officers concerned of Public Works Sub-Division, (North) Solapur on 21.09.2026 in the presence of Mrs. Manasi Joshi- Principal, Indian Model International School, Solapur of the school and that the building/premises is fit for occupancy for running school with effect from **2026-2027** for a period of **01** years in accordance with rule and subject to compliance of the specific conditions as appended. The building safety certificate is being issued for a period of one year, subject to the following conditions.

1. All structural members of the building shall be maintained in sound and safe condition. Any cracks, deterioration, or damage noticed during the validity period shall be repaired immediately.
2. This Certificate is issued only on the basis of the visual inspection of the building and documents produced by the applicant.
3. This Certificate does not certify the structural design or quality of construction beyond the scope of the inspection carried out.
4. The school management shall comply with all provisions of the National Building Code (NBC), applicable Indian Standards (IS Codes), and directions issued by the competent authorities from time to time.
5. A structural audit of the building should be conducted by a competent and authorized structural engineer as required. Necessary repairs, strengthening, and maintenance works, based on the recommendations of the audit report, must be completed periodically to keep the building in a safe condition.

**" Countersign"**

**Assistant Engineer Grade-1,**
**P.W.Sub division (North), Solapur.**

M Joshi
**Principal**
Indian Model International School
Solapur

**Executive Engineer,**
**Public Works Division, Solapur**

Executive Engineer
Public Works Dn. Solapur

Manager
Indian Model International School
Solapur